



# FACILITY COMPLIANCE AUDIT REPORT

## Division of Waste Management

### Solid Waste Section

**UNIT TYPE:**

Lined MSWLF		LCID	<b>X</b>	YW		Transfer		Compost		SLAS		COUNTY: Warren
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: NO694
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

**Date of Audit:** September 13, 2007**Date of Last Audit:** August 2, 2007**FACILITY NAME AND ADDRESS:**

Myrick LCID  
Eaton Ferry Road  
Littleton, NC

**GPS COORDINATES:** N: 36.47562 W: 77.98784**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Jay Myrick  
Telephone: 252-586-7783  
Email address:  
Fax:

**FACILITY CONTACT ADDRESS:**

Jay Myrick  
10315 Hwy 158  
Littleton, NC 27850

**AUDIT PARTICIPANTS:**

Mary Whaley, NCDENR, Solid Waste

**STATUS OF PERMIT:**

Notification dated April 28, 2006. The property is recorded in Deed Book 00816, Page 0170.

**PURPOSE OF AUDIT:**

Partial audit

**NOTICE OF VIOLATION(S):**

NONE

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**STATUS OF PAST NOTED VIOLATIONS:**

- 1. 15A NCAC 13B .0566 (12)** states "Open burning of solid waste is prohibited." The site had a fire which the owner/operator, Jay Myrick stated was started by lightning. The fire was completely out. **RESOLVED**
- 2. 15A NCAC 13B .0566 (4)** states "Adequate soil cover shall be applied monthly, or when the active area Reaches one acre in size, whichever occurs first." The waste has been covered with adequate soil. **RESOLVED**

**FACILITY COMPLIANCE AUDIT REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

3. **15A NCAC 13B .0565 (3) (j)** states "Excavation, grading, and fill material side slopes shall not exceed three to one (3:1)." The side slopes were steeper than 3:1. The side slopes were at no greater a slope than 3:1.  
**RESOLVED**

**AREAS OF CONCERN AND COMMENTS:**

1. Access roads were acceptable.
2. There is a sign and a gate that is kept locked to prevent unauthorized dumping.
3. There was unacceptable debris within the 100 foot setback from the under two acre area of disposal. This 100 feet should be kept clear of logs to be cut for firewood, tin roofing, etc

Please contact me if you have any questions or concerns regarding this audit report.



Phone: 919-693-5023

Mary Whaley  
Environmental Senior Specialist  
*Regional Representative*

Delivered on : <u>September 17, 2007</u> by		Hand delivery	<b>X</b>	US Mail		Certified No. <u>  </u>
---	--	---------------	----------	---------	--	-------------------------

cc: Mark Poindexter, Field Operations Branch Supervisor  
Dennis Shackelford, Eastern District Supervisor  
Donald Herndon, Compliance Officer